

### **Crystal Tower**

2023

csharpe.com







- Over 40 years of experience specializing in complex exterior restoration
- Operating in harsh coastal areas and conditions since our inception
- Work on occupied buildings around owners, guests, and customers
- Extensive expertise in various products and systems
- Seek long-term relationships and repeat business
- Specialize in working with design professionals to provide solutions to complex problems




### **Complex Exterior Restoration**



### 2022-2023 Project Timeline





# **Crystal Tower Condominium**

1010 W Beach Blvd. Gulf Shores, AL 36542

- Metal Roof Replacement on Stairwells & Elevator
   Tower
- Elevator Tower Metal Framing Repairs
- Elevator Tower Framed Stucco Wall Replacement
- New Control Joint Locations
- New Louver Shrouds
- New Coatings / Sealants
- Supported Investigative Work with Thompson Engineering










# **Crystal Tower Condominium**

1010 W Beach Blvd. Gulf Shores, AL 36542

- Metal Roof Replacement on Stairwells & Elevator
   Tower
- Elevator Tower Metal Framing Repairs
- Elevator Tower Framed Stucco Wall Replacement
- New Control Joint Locations
- New Louver Shrouds
- New Coatings / Sealants
- Supported Investigative Work with Thompson
   Engineering





# **Crystal Tower Condominium**

1010 W Beach Blvd. Gulf Shores, AL 36542


- Metal Roof Replacement on Stairwells & Elevator
   Tower
- Elevator Tower Metal Framing Repairs
- Elevator Tower Framed Stucco Wall Replacement
- New Control Joint Locations
- New Louver Shrouds
- New Coatings / Sealants
- Supported Investigative Work with Thompson
   Engineering




## Thank You


csharpe.com


#### **North Stucco Elevation**













1 CRYSTAL TOWERS VENT COVERS
SCALE: NTS

#### **East Elevation**









#### **East Windows**









